



Czujnik światła stop hamulca tylnego

Nr OEM Suzuki: 37740-31D00-000 / 37740-45D00-000

Zastosowanie SUZUKI:

DL 650 V-Strom 2004-2018
DL 1000 V-Strom 2002-2018
DR 125 SM 2008-2013
DR 125 SE 1995-2000
DR 350 SE 1994-1999
DR 650 R/RE/RSE 1992-1996
DR 650 R 1992



DR 800 Big 1994-1999
GN 125 1994-1999
GN 250 1994-1999
GSR 600 2006-2011
GSR 750 2011-2017
GSX 750 Inazuma 1998-2003
GSX 1100 1994- 1996
GSX 1200 Inazuma 1999-2000
GSX 1300 B-King 2008-2012
GSX-R 600 2004-2010
GSX-R 750 1992-2010
GSX-R 1000 2005-2016
GSX-S 750 2017-2018
GSX-S 1000 2015- 2017
LS 650 Savage 1997-2000
RG 125 Gamma 1992
RV 125 Van Van 2003-2017
RV 200 Van Van 2016- 2017
SV 650 1999-2016
SV 1000 2004-2005
TL 1000 S 1997-2000
TU 125 XT 1999
TU 250 X Volty 1997-2001
VS 600 Intruder 1995-1997
VS 800 Intruder 1992-2000
VX 800 1993-1997
VZ 800 Marauder 1997-2003

ID: 2964